

Error Code 14

Explanation: Overheat Film Wrap has activated. There may be a hot spot on the heat exchanger that has caused the overheat film wrap to fault. At a minimum check the following:

1. Check gas type of unit and ensure it matches gas type being used.
2. Check heat exchanger for cracks and/or separations.
3. Check for restrictions in airflow around unit and vent terminal.
4. Check for a foreign materials in exhaust venting.
5. Before checking resistance of Molex connections, remove the Molex from the circuit board.

