

Error Code 15

Explanation: Boiling Safety Device. The heat exchanger is too hot. At a minimum check the following:

1. Check for restrictions in airflow around unit and vent terminal.
2. Check for a foreign materials in exhaust venting.
3. Back flush the unit to remote any sediment of buildup in the heat exchanger.

See section on how to display maintenance information.

